



Quality • Innovation • Reliability

PROTECTION AGAINST FREEZING INSIDE ROLEC PEDESTALS

Whilst all Rolec pedestals containing water systems come complete with lagging as standard, lagging on its own will not always protect against freezing in sub-zero temperatures.

To assist against pipe freezing we are able to upgrade the water system to include self-regulating heat trace tape.

- Connects directly to mains electrical supply inside the pedestal
- Self-regulating temperature control (no thermostat required)
- Heat trace tape can be cut to length to suit each application
- Very low operating cost
- Heat trace tape systems are available for the marina's entire water system

Note: It is always recommended that a marina's water system is drained in the event of freezing temperatures.

YOU SPECIFY IT - WE BUILD IT



t: ++44 (0)1205 724754
f: ++44 (0)1205 724876
rolec@rolecserv.co.uk

Rolec Services Ltd,
Ralphs Lane,
Frampton West, Boston,
Lincs, UK. PE20 1QU

www.rolecserv.com

